




DESIGN GUIDE

CNC Machining



6-cnc.com



Table of Contents

2 Overview

- What is CNC machining?
- CNC Milling Machines
- CNC Lathes

5 CNC Manufacturing Standards

- General Manufacturing Standards
- General Tolerances
- Part Tolerances
- Size Limitations
 - Mill Parts
 - Lathe Parts
 - Material Blank Size

10 Design Guidelines

- Part Complexity
- Fillets
 - Inside Corner Fillets
 - Floor Fillets

Holes

- Standard Drill Sizes
- Hole Depth to Diameter Ratio
- Other Hole Design Tips
- Pockets and Cavities
- Wall Thickness
- Threads & Tapped Holes
- Embossed & Engraved Text
- Undercuts

19 Materials and Post-Processing

- Metal Materials
- Plastic & Composite Materials
- Inserts
- Part Markings
- Finishes

24 Additional Resources

- Quick Design Reference Chart
- Additional Resources at 6CNC

A close-up, high-angle shot of a CNC machine's end mill cutting into a metal workpiece. The machine is dark, and the workpiece is a light-colored metal. A large amount of fine metal chips is being removed from the workpiece, creating a misty spray. The background is blurred, showing other parts of the machine and the workshop environment. The overall color scheme is dark blue and black, with the text in white.

CNC MACHINING


Overview

Introduction


What is CNC Machining?

CNC (Computer Numerical Controlled) Machining is a means to remove material using high speed, precision machines that use a wide variety of cutting tools to create the final design. CAM (computer aided manufacturing) software, in conjunction with the CAD (computer aided design) model provided by the customer, is used to program the instructions the machines will use to produce parts.

Because a computer controls the machine's movement, the horizontal, vertical, and rotational axes can all move simultaneously to create everything from simple straight lines to complex geometric shapes. However, despite advancements in tooling and CNC controls, some limitations still exist in CNC machining, and not all profiles and features can be created. These limitations will be discussed later in this guide.




What is CNC Machining?



CNC Milling Machines

With CNC mills, parts are manufactured by holding down the stock material or workpiece to the machine bed while a fast-turning spindle holding the cutting tool removes material. Horizontal and vertical movements of the spindle and bed are used to manipulate the workpiece's position, allowing various shapes and depths to be cut. In machines with an additional axis of control, such as the rotary axis in 5-axis machines, the tooling can access multiple faces and hard-to-reach areas to create complex features with reduced setups.



CNC Lathes

Complex cylindrical shapes can be manufactured more cost effectively using a CNC lathe versus a 3 or 5-axis CNC milling machine. With a CNC lathe, the part stock turns while the cutting tools remain stationary. To create the geometry of a part, the CNC computer controls the rotational speed of the stock, as well as the movement and feed rates of the stationary tools. If square features are required on an otherwise round part, typically, the round geometry is created first using a lathe, then the part is moved to a milling machine to create the square features. Lathes with live or driven tools take exception to this and can perform certain milling operations such as drilling, slotting, and tapping within the lathe itself.

A close-up, high-angle shot of a CNC machine's end mill cutting into a metal workpiece. The machine is dark, and the workpiece is a light-colored metal. A large amount of metal shavings is being removed, creating a cloud of chips around the cutting point. The background is blurred, showing other parts of the machine and the workshop environment.


CNC MACHINING

CNC Machining Standards

General Manufacturing Standards

Unless otherwise specified, 6CNC manufactures CNC machined components to the following standards:

- As-machined surface finish is Ra 3.2 or better. Machine tool marks may leave a swirl-like pattern.
- Sharp edges will be broken and deburred by default. Critical edges that must be left sharp should be noted and specified on a print.
- Clear or transparent plastics will be matte or have translucent swirl marks on any machined face. Bead blasting will leave a frosted finish on clear plastics.
- Tolerances on foam or similar compressible materials cannot be guaranteed.



A part with a standard finish, cleaned and deburred. Milling and tool marks may be visible with a Ra 3.2 μm finish.

General Tolerances

Tolerance is the acceptable range for a dimension which is determined by the designer based on the form, fit, and function of a part. Unless specifically called out by the designer, 6CNC will follow industry standard ISO 2768 and ISO 286 tolerances listed below:

Did you know...

A piece of printer paper is about 0.10 mm thick!



Tolerance Standard	General Linear Tolerances	General Tolerances for External Radius and Chamfer Heights	Angular Dimensions
ISO 2768 – Medium (Standard)	±0.1-2 mm depending on the nominal length from 0.5 to over 2000 mm	±0.2-1 mm depending on the nominal length from 0.5 to over 6 mm	±1°-0°5' depending on the nominal length from up to 10 to over 400 mm
ISO 2768 – Fine	±0.05-0.5 mm depending on the nominal length from 0.5 to over 2000 mm	±0.2-1 mm depending on the nominal length from 0.5 to over 6 mm	±1°-0°5' depending on the nominal length from up to 10 to over 400 mm
ISO 286 – Grade 8	Standardized tolerance value ranges from 0.014 to 0.23 mm depending on the nominal size from 0.5 to 2000 mm		
ISO 286 – Grade 7	Standardized tolerance value ranges from 0.010 to 0.150 mm depending on the nominal size from 0.5 to 2000 mm		
ISO 286 – Grade 6	Standardized tolerance value ranges from 0.006 to 0.092 mm depending on the nominal size from 0.5 to 2000 mm		

Note: These tolerances apply to machined metal components. The tolerance grades for plastic and composite materials are ISO 2768 coarse or medium for general tolerances, and ISO 286 grade 8 or bigger for specific tolerances.

If tighter tolerances (less than the standard, e.g. ±0.1-2 mm) are required, information regarding which dimensions require tighter tolerances must be communicated. A technical drawing or specification sheet is the best way to share this information.

Tight Tolerances

General tolerances for CNC machining are typically starting at ± 0.1 mm. Tight tolerances typically describe tolerances smaller than the general standard. With CNC machining, we can achieve tolerances as tight as ± 0.01 mm. With specialized setups and additional operations such as reaming, grinding, etc., even tighter tolerances are possible for some features depending on the material and part geometry. Overall geometric tolerances (GD&T) can also be applied to the drawing for the part; however, these may lead to longer inspection times due to the tools and time required to check them.

While tighter tolerances can benefit a part's form, fit, and function, some disadvantages go along with them. Tighter tolerances can lead to higher scrap rates, additional fixturing, special measurement tools, and longer cycle times from slower cutting speeds, all of which can cause pricing and lead times to increase. Depending on the tolerance call out and its geometry, the part cost can be more than double what it would be with a standard tolerance.



Pro Tip:

To help minimize cost and lead time, apply tight or geometric tolerances exclusively to critical areas and only specify what is required to meet your part's form, fit, and function.

Size Limitations

Milled Parts

Part size is limited to the machine's capabilities and depth of cut required by a part's features. 6CNC can typically mill parts up to X-2000 mm, Y-750 mm, Z-600 mm. The features and size of each unique part will determine that part's machinable height. If your part goes beyond 24" in machinable height, it will require an additional manual review for manufacturability.


Lathe Parts

6CNC's capabilities allow for turned parts up to D-500 mm, L-4500 mm. In addition to standard 2-axis lathes, 6CNC's manufacturing facilities utilize specialized equipment such as live tooling systems, multi-spindle machines, and swiss lathes, which are great for producing lathe parts with milled features or small, delicate features.

Material Blank Size

"Material blank" or simply "blank" refers to the size of the raw material used to create the finished part. Blanks typically need to be slightly larger than the finished part's measurements to allow for variations in the raw material and to cut away the rough faces of the raw material. For example, if the final dimensions are to be 20 x 20 x 20 mm, then a suitable blank for the part would be roughly 23 x 23 x 23 mm.

Designers should keep blank sizes in mind when designing their parts. Optimising your design to allow for smaller and standardized blank sizes is a good way of reducing part cost and waste. Remember that some blank sizes are more common in particular materials than others.



A close-up, high-contrast photograph of a CNC machine's end mill cutting into a metal workpiece. The scene is filled with metallic shavings and sparks, creating a dynamic and industrial atmosphere. The lighting is dramatic, highlighting the textures of the metal and the precision of the machinery.

CNC MACHINING


Design Guidelines

Part Complexity

Part Complexity

CNC machining can effectively produce highly complex designs; however, that does not mean you should not strive to simplify your designs. A part with contoured geometry or multiple faces that need to be cut will typically take longer to machine and thus have a higher cost when compared to a piece that only requires one setup and three axes (X, Y, and the tool movement of the Z). Minimal cuts are made with small tools to create a complex curved surface with a suitable surface finish. These tiny cuts take significantly longer to machine than the more significant cuts that can be made on broader or planar geometries, increasing the cost.

To help minimize cost and machining time, try to design parts using on-axis planes as much as possible. Avoid unnecessary draft angles and contoured or organically shaped geometry. Minimizing feature variations, such as internal corner radii and tapped holes, will also help reduce tool changes, thus further saving time and cost through a simplified design.



Fillets


When using a CNC vertical or horizontal milling machine, interior vertical walls cannot be left sharp and will be machined with a radius. Radii must be present because the material is removed using a round tool spinning at high RPMs. Part designers must consider where radii will occur due to this limitation.

Inside Corner Fillets

When it comes to inside corner fillets, the radii size is key. Sizing corner radii appropriately can improve not only cutting efficiency and cost but quality as well. Consider the following for internal corner radii in your designs:

- ✓ Use a radius that does not correlate with standard tool sizes
- ✓ Radii should be above 0.5 mm
- ✓ Use as large a radius as possible
- ✓ Avoid small, deep radii

Most cutting tools come in standard sizes, such as Ø12, Ø6, Ø3, etc.. Avoid these standard sizes; if the tool radii match the designed corner radii, it will not have the proper clearance to turn into the cut. Instead, the tool must come to a complete stop, pivot 90 degrees, then resume cutting. These abrupt cutting paths reduce efficiency and lead to quality issues such as chatter.



Larger radii also enable bigger tools for machining the parts that remove more material with each cut, reducing machine time and overall cost. When the cut's depth exceeds two times the diameter of the cutting tool, the tool's feed rate must slow down, increasing the cycle time and part cost. Though small radius tools (down to a 0.25 mm radius) are available, sometimes the depth of cut required makes it impossible because the tool is not manufactured in the required length. Even if the tool exists, the part cost will increase significantly due to the extra manufacturing time required to machine a part using only minuscule cuts.

Pro Tip:

Use a radius 1.3 times the radius of the closest standard tool size and aim for a radii-to-depth ratio of 1:4 for pocket radii. A smaller radius of 1:8 is also possible to a certain extent, but it would increase the machining time and thus the cost.

Floor Fillets

Generally speaking, floor fillets can be time-consuming and difficult to machine and thus should be avoided unless vital to your part's form and function. When creating a floor radius that meets a corner, it is much easier to machine if the floor radius is smaller than the wall radius. By having the floor radius smaller than the wall radius, the same tool can be used to remove the material, which creates a smooth flow through the corner.

Pro Tip:


For better manufacturability of floor fillets, use a standard bull nose mill radius.

Holes

Holes are typically created using drill bits that plunge into the workpiece to remove material. Drilling is a fast and efficient method of creating holes and is what most machinists will defer to when they can. More significant or oddly sized holes can be made via helical milling with an endmill, but this is slower and less efficient than drilling methods. In either case, designers should make a few considerations when designing holes in their parts.


Standard Drill Sizes

Designers should become familiar with standard drill bit sizes and design holes to match, allowing fast drilling and accurate hole sizes. Non-standard sizes may require expensive custom tooling or additional passes with endmills and reamers to achieve the dimension, which increases cycle time. The standard metric drill size is an increment of 0.1 mm from 1 mm to 13 mm. Anything bigger than 13 mm is usually an increment of 0.5 mm.



Hole Depth to Diameter Ratios

As the depth of a hole increases, so does the manufacturing difficulty. Excessively deep and narrow holes can lead to manufacturing issues such as tool breakage, drill walking, and chip evacuation issues, among others. Hole depth to diameter should be kept as low as possible. Holes with significant depth-to-diameter ratios may require specialized tooling, such as gun drilling, to achieve the geometry.



Pro Tip:

Pick hole sizes that work universally. Lowering hole size variation means the same tool can be used for multiple features, reducing cycle time and cost.

Pro Tip:


Keep your drill hole diameter-to-depth ratio below 1:10 for manufacturability. Even better is a time and cost-saving ratio of 1:4. For example, a 6 mm diameter drilled hole at 24 mm deep is optimal, while a depth of 60 mm is achievable.

Holes

Other Hole Design Tips

Here are some other quick tips and considerations you can follow to improve hole manufacturability of your parts:

- ✓ Avoid partial (e.g., on edge) holes; these are difficult to manufacture. If necessary, keep at least 75% of the hole inside the part edge.
- ✓ Keep holes and pockets at least 0.8 mm from walls to avoid defects in metal parts. This value doubles for milled plastic or composite materials.
- ✓ Keep the hole axis perpendicular to the surface; avoid drilling on sloped or curved surfaces. Adding a flat to curved surfaces where the hole is will ensure the drill enters perpendicularly.
- ✓ Use through holes over blind holes when possible; they are more accessible to machine, ream, and tap.
- ✓ If you need to use blind holes, add 25% additional depth than you require to account for drill points and chip evacuation.
- ✓ Avoid designing holes that intersect with cavities, which can lead to manufacturing issues. If an intersection is unavoidable, keep the center of the drill axis away from the cavity.



Design Guidelines



Pockets and Cavities

Pockets and excessively deep cavities can pose manufacturing issues such as tool deflection, chip evacuation problems, and tool breakage. Cavities greater than six times deep than they are wide are considered too deep; the ideal width-to-depth ratio is $D < 4W$.

If you require deeper cavities, consider using a variable cavity width that is wider at the top allowing for better tool access at the bottom.

Pro Tip:

When a straight rectangular part will be assembled into a cavity, and a sharp corner is desired, adding corner reliefs or dog bone cuts is better than using a small radius.




Design Guidelines

Threads and Tapped Holes

There are several ways to create threads in a part: cut taps, form taps, or thread mills. All of these methods are effective, but designers should keep the following in mind:

- ✓ Only thread to the length necessary; going beyond twice the hole diameter is not usually needed for metals. Deep, threaded holes can increase the part cost as specialized tooling may be required to meet the depth requirements.
- ✓ Consider using threaded inserts for softer materials such as aluminium or plastics.
- ✓ Always choose the largest thread size allowed by design—making the manufacturing process more manageable.
- ✓ The smaller the tap, the greater the chance it will break during production. Threads below M2 in size become risky to form due to a high potential for tool breakage.
- ✓ Avoid using uncommon or custom thread specifications; these may require costly taps or custom tools.
- ✓ For blind holes, add an unthreaded length of at least half the diameter of the hole after the thread to allow for tap lead and chip evacuation. It is not necessary to design a drill relief into the 3D model but should be called out as allowable on a technical drawing.
- ✓ Add threads to your quote and attach a specified drawing to communicate your requirements. Drawing specifications should fully define the tapped feature, including thread type, hole size and depth, and any blending treatment, such as countersinks.



$L < 2 \times \text{Diameter}$

Wall Thickness and Machined Text

Wall Thickness

Walls should be kept thick enough to ensure strength and rigidity. When thicknesses become excessively thin, they are prone to warping, breakthrough, and general failure when under stress. Additionally, as rigidity is lost, vibrations from the machining process can result in chatter, forcing the machinist to slow things down to mitigate this issue. It is also more difficult to maintain accuracy when cutting walls that are not rigid enough due to being too thin.

Minimum wall thickness should correspond with the following:

- ✓ Metal Materials: 0.794 mm
- ✓ Plastic & Composite Materials: 1.5 mm

Machined Text

Machined text can be designed in one of two ways: embossed text that rises above the surface or engraved text that sits below the surface. Of these methods, we recommend creating text as engraved instead of embossed. Engraving requires minimal material removal, unlike embossing, which involves a large amount of material removal adjacent to the text to create the embossed effect. If you do not require machined markings, consider laser marking as an alternative method for adding text to your part.

Pro Tip:

Use **20-point sans serif fonts** and remember any sharp internal edges of characters will be machined with a radius.

Metals



$W > 0.794 \text{ mm}$

Plastics



$W > 1.5 \text{ mm}$



Embossing ✗




Engraving ✓

Undercuts

Some features cannot be reached by a standard machining tool, thus creating an undercut region on the part. Care must be taken when designing an undercut for two reasons:

First, suppose the feature dimension does not correlate to a standard cutter size. In that case, the undercut may require creating a costly custom tool, causing part cost and lead time to increase significantly—especially if only a few parts are to be manufactured. If a standard radius were to be used, the price is greatly reduced since standardised tooling can be used.

Second, there are limits to the cut depth due to the tool's construction (typically a keyseat cutter, a horizontal cutting blade attached to a vertical shaft). There is no “standard depth” for undercuts, but the shallower the better. Designing undercuts in accessible places is also critical. The figure to the right depicts an undercut feature that cannot be manufactured via a machining process.



A close-up, high-contrast photograph of a CNC machine's end mill cutting into a metal workpiece. The scene is filled with bright sparks and fine metal shavings, creating a dynamic and industrial atmosphere. The lighting is dramatic, highlighting the textures of the metal and the precision of the machinery.

CNC MACHINING

Materials and Post-Processing

Standard Materials

Material selection is critical in determining a part's overall functionality and cost. The designer must determine the material characteristics key to the part's design – hardness, rigidity, chemical resistance, heat treatability, thermal stability, etc. 6CNC machines a wide variety of metal and plastic materials, listed below, and other custom materials upon request.



Metal Materials

- Aluminum
- Brass
- Bronze
- Copper
- Carbon Steel
- Stainless Steel
- Nitronic 60
- Titanium
- Other custom metals



Plastic & Composite Materials

- | | |
|--------------------------|-------------------------|
| • ABS | • PTFE |
| • POM / Acetal (Delrin®) | • PVC |
| • Acrylic | • UHMW PE |
| • HDPE | • Ultem |
| • Nylon / PA | • Other custom plastics |
| • PEEK | |
| • Polycarbonate | |
| • Polypropylene | |

Material type is a critical driver in determining the overall cost of a part. Plastics and softer metals (e.g. aluminium and brass) in general machine easily and subsequently require less machine time, reducing the cost of machining. Harder materials like stainless steel and carbon steel must be machined with slower spindle RPMs and machine feed rates which makes for longer cycle times over the softer materials. As a baseline estimate, aluminium will be machined about 4 times faster than carbon steel, and stainless steel will be machined half as fast as carbon steel.

Plastic can be a less expensive alternative to metal if a part's design does not require the rigidity of metal. Polyethylene, for example, is easy to machine and is about 1/3 the cost of 6061 aluminium.

Note: Depending on a part's geometry, tight tolerances can be harder to hold with plastics. Parts may also warp after machining due to the stress created when material is removed.

Inserts

Inserts are a common method for creating strong, reliable threads in parts. They are especially useful in softer materials such as aluminium or plastics, where tapped threads are more prone to wear and tear. If you require inserts, be sure to list the number of inserts required per part on your quote. 6CNC and its manufacturing partners regularly install inserts such as:

- Helica/Helicoil Inserts
- Key-Locking Inserts
- Press-Fit/Self-Clinching Inserts
- Heat-Set Inserts
- Tapping Inserts

When designing for inserts, follow the guidelines specified by the instructions included with the off-the-shelf inserts. Make sure to note the part SKU and install direction in an accompanying print for reference.



Pro Tip:

Do not upload your CAD model with inserts included as an assembly; machinists will defer to technical drawings for insert callouts. Embedding inserts into your CAD file can cause problems with instant quoting and CNC programming.

Part Markings

Part marking is a great way to add high-contrast markings, part numbers, logos, and more. The table below compares the different types of marking methods we offer.

Marking Method	Common Uses	Pros	Cons
Laser Marking and Engraving	• Graphics • Part numbers • Text	• Extremely durable markings • Crisp detail	• Cannot produce coloured markings
Bag and Tag	• Serialisation • Part numbers • Bulk packaging	• Very low cost • Can speed up inventory and receiving processes	• Non-permanent solution

NOTE: For markings with special font, graphics or logos, please provide artwork files in the form of a vector file such as a DXF; pixelated or raster files are not suitable.

Finishes

Applying a finish to your machined parts can not only improve their cosmetic appeal but also provide surface protection and increased performance. Below you will find some of the post-processing options and finishes we offer.



Anodizing

- Type II Anodize (Standard)
- Type III Hard coat / Hard Anodizing
- Type III w/ PTFE



Metal Plating

- Electroless Nickel
- Zinc
- Gold
- Silver



Adhesives and Coatings

- Black Oxide / Blackening
- Powder Coating



Conversion and Pretreatments

- Chem Film
- Chromate
- Conversion Coating
- Heat Treat
- Case Harden
- Passivation
- Pickle and Oil
- Bead Blasting
- Electropolishing
- Phosphatation


A close-up, high-contrast photograph of a CNC machine's end mill cutting into a metal workpiece. The scene is filled with metallic shavings and sparks, creating a dynamic and industrial atmosphere. The lighting is dramatic, highlighting the precision of the manufacturing process.





CNC MACHINING

Additional Resources at 6CNC

References

Quick Design Reference Chart



	Design Feature	Guideline	Comments
1	 Interior corner fillet	$R_{\text{depth}} \div R_{\text{edge}} \leq 4$ $R_{\text{edge}} = 1.3 * R_{\text{tool}}$	The larger the radii, the lower the cost
2	 Floor Fillet	Less than wall radii	Increase manufacturability using standard ball nose mill sizes
3	 Hole Diameter-to-Depth Ratio	Less than 1:10	A ratio of 1:4 is optimal
4	 Thread Depth	$\text{Length} < 2 * \text{Diameter}$	Consider using inserts for plastics
5	 Additional Hole Depth	25% additional depth after threads and inserts	Allows room for tool leads and chip evacuation
6	 Cavity Width-to-Depth Ratio	$\text{Depth} < 4 * \text{Width}$	Use corner reliefs where tight assembly fits are needed
7	 Wall Thickness	Metals $\geq 0.794 \text{ mm}$ Plastics $\geq 1.5 \text{ mm}$	Avoid designing walls at minimum thickness, thicker is better
8	 Machined Text	20pt + Sans-Serif	Use machine engraved text instead of embossed text for lower costs
9	 Edge Chamfer	45°	Use chamfers instead of fillets for edge breaks to lower cost

Additional Resources at 6CNC

Online Instant Quoting

- **Web:** Upload your CAD file at <https://6-cnc.com/>
- **Accepted file types:** STEP (.step, .stp), SOLIDWORKS (.sldprt), Mesh (.stl), Parasolid (.x_t, .x_b), DXF (.dxf), Autodesk Inventor (.ipt), Dassault Systems (.3dxml, .catpart), PTC, Siemens (.prt), ACIS (.sat)
- **Other Capabilities:**



CNC
Machining



Sheet Metal
Fabrication



3D Printing



Vacuum
Casting



Injection
Moulding



Die Casting

Other CNC Machining Resources

- [Size Limitations in CNC Machining](#)
- [Tolerances in CNC Machining](#)
- [Selecting The Right Surface Roughness](#)
- [Video: How To Prepare A Perfect Technical Drawing](#)
- [How To Choose The Right Material](#)
- [Surface Finishes For CNC Machining](#)

Contact Details

- **Web:** <https://6-cnc.com/>